




Sample Report

24-Jul-22 9:43:23 AM


°C 24-Jul-22 9:43:23 AM



FLIR0016.jpg

FLIR E5

639054660



FLIR0016.jpg


FLIR E5

639054660

Pipe connection upto certain depth and leakage among them can be seen easily.

01-Jan-10 4:39:00 AM


°C 01-Jan-10 4:39:00 AM



FLIR1282.jpg

FLIR E5

639054660



FLIR1282.jpg


FLIR E5

639054660

Flooding - water wicking up a wall and damaging down wall studs.

10-Dec-19 10:31:07 AM


°C 10-Dec-19 10:31:07 AM



Leakage due to waste drainage pipe.


24-Jul-22 12:31:01 PM

°C 24-Jul-22 12:31:01 PM



Terrace:- Water leakage due to loose joints of tiles and water tank leakage.

01-Jan-10 2:24:43 AM



FLIR1209.jpg

FLIR E5

639054660

°C 01-Jan-10 2:24:43 AM




FLIR1209.jpg

FLIR E5

639054660

Walls - top-down triangular shape formed as water spreads downwards.

10-Dec-19 10:42:20 AM




FLIR0046.jpg

FLIR E6

639003009

°C 10-Dec-19 10:42:20 AM



FLIR0046.jpg


FLIR E6

639003009

Ceiling - amorphous, unstructured shape with areas of wet, damp, and moist material spreading outwards with different temperatures.

01-Jan-10 4:04:08 AM

°C 01-Jan-10 4:04:08 AM



FLIR1275.jpg

FLIR E5

639054660FLIR1275.jpg


FLIR E5

639054660

Water leakage due to hand wash basin.

01-Jan-10 1:28:28 AM

°C 01-Jan-10 1:28:28 AM



FLIR1252.jpg

FLIR E5

639054660FLIR1252.jpg

FLIR E5

639054660

Washroom:- Water leakage due to sunken slab and floors.